

# Wireline Re-Entry Guide - Half Mule Shoe

The Brio-Tech Pressure Controls Wireline Re-Entry Guide Mule Shoe is utilized on the bottom of the tubing string to allow for re-entry of wireline tool strings, or E-line logging strings back into the tubing string.

**Applications:**

The Brio-Tech Pressure Controls Wireline Re-Entry Guide Mule Show is beneficial in deviated well bores, or in any instance where bottom of the tubing may not be concentric to the wellbore.

Size	1.660"	2.062"	2.375"
Upper Thread Conn.	1.660 NUE Box	1.900 EUE Box	2 3/8" EUE Box
Lower Thread Conn.	n/a	n/a	n/a
Maximum OD (")	2.20"	2.50"	3.062"
Maximum OD (mm)	55.88 mm	63.50 mm	77.77 mm
Minimum ID (")	1.38"	1.61"	1.99"
Minimum ID (mm)	35.05 mm	40.89 mm	50.565 mm

Size	2 7/8"	3 1/2"	4 1/2"
Upper Thread Conn.	2 7/8" EUE Box	3 1/2" EUE Box	4 1/2" EUE Box
Lower Thread Conn.	n/a	n/a	n/a
Maximum OD (")	3.668"	4.50"	5.563"
Maximum OD (mm)	93.17 mm	114.30mm	141.30mm
Minimum ID (")	2.441"	2.99"	3.958"
Minimum ID (mm)	62.00 mm	75.94mm	100.53mm



Contact your Brio-tech representative for more information

BRIO-TECH PRESSURE CONTROLS - 3904 – 53RD AVENUE NW, EDMONTON, ALBERTA, CANADA T6B 3N7  
(780) 670-2020

PLEASE STATE PART DESCRIPTION AND SIZE WHEN ORDERING

